

ALARM ADDRESS	A10.2	ALARM NO.	1166
ALARM TEXT	ATC-ARM MOTOR OL.		
Polated Signal	Input: X7.5 (MV154/154APC/MV204) , X9.7 (184C) 。		
Related Signal	Output: Y1.0 , Y1.1 (MV154/154APC/MV204) , Y4.6 ,Y4.7(184C) •		
CAUSE	ATC-ARM Motor breaker is overl	21 ARM 2 ARM	ACCIDICADE D AC
ACTION	Turn on the breaker at cabinet as attached label indicated. • Cancel alarm by reset button On FANUC panel •		