## Alarm Help - MV SERIES -



ALARM ADDRESS	A15.6	ALARM NO.	2022
OP. MESSAGE	CURRENT POCKET CTR.(D22) AND MAG. HOME SENSOR NOT MATCH.		
	PLS CHK CTR SENSOR & DATA TABLE D22. AFTER CHK, PERFORM TL-TAB REGULATE.		
Related Signal	Input: X0.3 (MV154/154APC/MV204) , X6.3 (184C) 。		
CAUSE	Following may be occurred:		
	A. Current pocket NO. D22 equal 1, But magazine home proximity not detected $\circ$		
	B. Magazine home proximity has been detected, but current pocket NO. D22 not		
	equal 1 •		
ACTION	Perform tool table regulate •		