Alarm Help - MV SERIES -



ALARM ADDRESS	A3.3	ALARM NO.	1111
ALARM TEXT	NO COFIRM. OF MAG. PIN IN.		
Related Signal	Input: X1.0 (MV154/154APC/MV204) •		
	Output:Y3.2 (MV154/154APC/MV204) -		
	MAG lock pin in signal not detect.		
CAUSE	1, 33 44 33 136 137 38 39 39 39 30 50 60 60 60 60 60 60 60 60 60 60 60 60 60		
ACTION	1.pin in but not detected : adjust sensitivity distance		
	2.snesor not function properly.		
	3.check air pressure.		
	4.Check relay output		