## Alarm Help - MV SERIES -



ALARM ADDRESS	A3.5	ALARM NO.	1113
ALARM TEXT	MAG PIN IN/OUT BOTH ON.		
Related Signal	Input: X1.0 ,X1.1 (MV154/154APC/MV204) •		
CAUSE	MAG pin in/out sensor both on		
ACTION	Check sensor is damaged?		