Alarm Help - MV SERIES -



ALARM ADDRESS	A17.5	ALARM NO.	2037
OP. MESSAGE	PLS SWITCH APC MODE TO AUTO		
Related Signal			
CAUSE	The APC manual mode on the control has been pressed		
ACTION	To control panel,release APC manual button		