Alarm Help - MV SERIES -



ALARM ADDRESS	A24.5	ALARM NO.	2093
OP. MESSAGE	SPINDLE SPEED CONVERTION ERROR.		
Related Signal	Same as Al2092 described •		
CAUSE	Same as Al2092 described •		
ACTION	Same as Al2092 described •		