## Alarm Help - MV SERIES -



ALARM ADDRESS	A12.2	ALARM NO.	1182
ALARM TEXT	NOW => SPDL AT CLAMP POS.		
Related Signal	Input: X2.0 (MV154/154APC/MV2 Output: Y2.7 (MV154/154APC/MV2  Spindle tool clamp co	V204) , Y6.2 (184	
CAUSE	In ATC service mode, This is a prompt for operator •		
ACTION			