Alarm Help - MV SERIES -



ALARM ADDRESS	A3.4	ALARM NO.	1112
ALARM TEXT	NO COFIRM. OF MAG. PIN OUT.		
Related Signal	Input: X1.1 (MV154/154APC/MV204) -		
	Output:Y3.2 (MV154/154APC/MV204) •		
CAUSE	MAG lock pin in signal not detect.		
ACTION	1.pin out but not detected : adjust sensitivity distance		
	2.snesor not function properly.		
	3.check air pressure.		