## Alarm Help - MV SERIES -



ALARM ADDRESS	A27.0	ALARM NO.	1300
OP. MESSAGE	NO CONFIRM OF PLT UP.		
Related Signal	Input: X16.0 (154APC) • Output: Y8.1 (154APC) •		
CAUSE	Plate change process have problem .		
ACTION	MDI mode ,command M51 for pallet up, then check:  1.Y8.1 activated, pallet not up: check hydraulic pressure, solenoid valve and Y8.1 Relay.  2.Y8.1 activated, pallet up:check signal X16.0 and sensor status.		