## Alarm Help - MV SERIES -



ALARM ADDRESS	A9.0	ALARM NO.	1156
ALARM TEXT	HYDRAULIC PUMP OL.		
Related Signal	Input:X11.2 (MV154/154APC/MV204) 。 Output:Y7.5 (MV154/154APC/MV204) 。		
CAUSE	Hydraulic breaker is overload		
ACTION	Turn on the breaker at cabinet as attached label indicated. •  Cancel alarm by reset button  On FANUC panel •		