

Boot 1

Test the battery and AC adapter together to verify the laptop properly powers on. During this boot, the battery will be charging.

Boot 2

Test the battery and AC adapter together to verify the laptop properly powers on. During this boot, the battery will be charging.

Boot 3

Test the battery only to verify the suspect properly powers on. This boot should have a battery that is charged enough to allow a Windows test to take place without the battery dying.