

Project - Organizational & Procedural Measures

Aleksander Klap

08.06.2026

1 Organizational & Procedural Measures

1.1 User Roles

Three roles, enforced on PLCs, HMIs, controllers, and the robot (SR-06.2). All access uses individual accounts — no shared logins.

Role	Permissions	Typical User
Operator	Monitor HMIs, access Web Interfaces. No configuration or program changes.	Student running a session
Engineer	Upload/modify PLC programs and parameters, configure HMIs. Login through Engineering Workstation only.	Lab technician / Teacher
Administrator	Device configuration, user and certificate management, firewall and switch configuration.	Lab administrator

1.2 Backup Strategy

Backup Strategy is specified in SR-10 (see TODO).

- PLC programs, HMI configurations, and controller configs are backed up after every change.
- The MES database is backed up daily.
- Backups go to dedicated backup storage (VLAN 10) and a copy is kept offline.
- Recovery procedures are documented and tested at least twice per year.

1.3 Incident Response

- Detect — Anomalies surface from the Syslog collector and firewall denied-traffic logs (SR-08). Operators report unexpected station behaviour immediately.
- Contain — Isolate the affected device or VLAN (disconnect or firewall block). Stop the station if process safety is in doubt.
- Preserve — Keep logs and alarms.
- Recover — Restore PLC/HMI config or MES data from the last known-good backup (SR-10.4).
- Document — Record what happened, the cause, and the fix.