
m
- metallic bars
- servos




reachable zone
π
0
π



3D



SIDE



TOP



STEPPER & IN THE CENTER



SIDE



TOP



3D







FRONT



denser possible center recomended




MASS
IN
NORMAL
OUT
FRONT



FRONT



TOP



3D
NORMAL



3D
"PUSHED-IN"

PUSH-UP
BUTTONS *



ELECTROMAGNETS



FRONT



SIDE





"CRÉMAILLÈRE"







SIDE



FRONT

TOP





3D



SIDE



TOP

"POULIES"



3D













"fan"



"PISTONS"