


Docking: four methods, saved whole-step sx tubes



Docking: safety couples position and velocity; no valid one-dimensional safe band exists on sx.
All four nonlinear-property outcomes remain UNKNOWN. No independent NNCS certificate.