


### Bump Test Response Delay. Actuator ID 101 2023-11-08T07:53:32




### Bump Test Response Delay. Actuator ID 108 2023-11-15T15:57:30




#### Bump Test Response Delay. Actuator ID 227 2023-11-15T16:18:52




### Bump Test Response Delay. Actuator ID 227 2023-11-15T17:02:00




# Bump Test Response Delay. Actuator ID 108 2023-11-21T19:49:00




# Bump Test Response Delay. Actuator ID 235 2023-11-21T20:22:37




# Bump Test Response Delay. Actuator ID 330 2023-11-21T20:59:50




### Bump Test Response Delay. Actuator ID 410 2023-11-21T21:11:16




# Bump Test Response Delay. Actuator ID 218 2023-11-22T21:05:25




### Bump Test Response Delay. Actuator ID 227 2023-11-22T21:10:24




#### Bump Test Response Delay. Actuator ID 235 2023-11-22T21:14:45




#### Bump Test Response Delay. Actuator ID 410 2023-11-22T22:51:43




## Bump Test Response Delay. Actuator ID 238 2023-11-23T23:18:59




### Bump Test Response Delay. Actuator ID 327 2023-11-23T23:32:06




# Bump Test Response Delay. Actuator ID 327 2023-11-23T23:42:13




### Bump Test Response Delay. Actuator ID 330 2023-11-23T23:43:36




# Bump Test Response Delay. Actuator ID 330 2023-11-23T23:46:09




### Bump Test Response Delay. Actuator ID 410 2023-11-24T00:35:23




### Bump Test Response Delay. Actuator ID 235 2023-11-24T19:07:00




### Bump Test Response Delay. Actuator ID 238 2023-11-24T19:13:41




# Bump Test Response Delay. Actuator ID 327 2023-11-24T19:26:47




# Bump Test Response Delay. Actuator ID 327 2023-11-27T20:37:11




# Bump Test Response Delay. Actuator ID 327 2023-11-27T20:43:50




# Bump Test Response Delay. Actuator ID 327 2023-11-27T20:53:37




## Bump Test Response Delay. Actuator ID 327 2023-11-27T20:53:37




### Bump Test Response Delay. Actuator ID 410 2023-11-27T21:07:25




### Bump Test Response Delay. Actuator ID 410 2023-11-27T21:11:03




# Bump Test Response Delay. Actuator ID 327 2023-11-28T18:59:05




## Bump Test Response Delay. Actuator ID 235 2023-11-28T19:37:02




# Bump Test Response Delay. Actuator ID 327 2023-11-28T19:53:51




### Bump Test Response Delay. Actuator ID 410 2023-11-28T20:03:26




### Bump Test Response Delay. Actuator ID 411 2023-11-28T20:07:23




### Bump Test Response Delay. Actuator ID 238 2023-11-29T18:56:35




#### Bump Test Response Delay. Actuator ID 235 2023-11-30T09:45:47




### Bump Test Response Delay. Actuator ID 238 2023-11-30T09:47:07




# Bump Test Response Delay. Actuator ID 327 2023-11-30T10:00:38




## Bump Test Response Delay. Actuator ID 327 2023-11-30T10:00:38




## Bump Test Response Delay. Actuator ID 238 2023-11-30T21:19:59




## Bump Test Response Delay. Actuator ID 327 2023-11-30T21:33:30




### Bump Test Response Delay. Actuator ID 330 2023-11-30T21:35:09




## Bump Test Response Delay. Actuator ID 410 2023-11-30T21:41:58




## Bump Test Response Delay. Actuator ID 238 2023-12-05T09:34:55




### Bump Test Response Delay. Actuator ID 330 2023-12-05T09:49:53




#### Bump Test Response Delay. Actuator ID 218 2023-12-06T08:43:18




## Bump Test Response Delay. Actuator ID 235 2023-12-07T05:44:15




#### Bump Test Response Delay. Actuator ID 410 2023-12-08T19:46:50




## Bump Test Response Delay. Actuator ID 215 2023-12-08T19:52:26




## Bump Test Response Delay. Actuator ID 222 2023-12-08T20:04:27




## Bump Test Response Delay. Actuator ID 227 2023-12-08T20:10:53




## Bump Test Response Delay. Actuator ID 235 2023-12-08T20:25:21




### Bump Test Response Delay. Actuator ID 330 2023-12-12T11:12:56




## Bump Test Response Delay. Actuator ID 305 2023-12-13T10:52:47




## Bump Test Response Delay. Actuator ID 308 2023-12-13T10:54:10




## Bump Test Response Delay. Actuator ID 410 2023-12-13T11:11:15




## Bump Test Response Delay. Actuator ID 305 2023-12-14T07:26:07




## Bump Test Response Delay. Actuator ID 410 2023-12-14T07:44:29




## Bump Test Response Delay. Actuator ID 305 2023-12-16T10:00:41




### Bump Test Response Delay. Actuator ID 218 2023-12-19T11:13:47




#### Bump Test Response Delay. Actuator ID 410 2023-12-19T11:43:43




## Bump Test Response Delay. Actuator ID 235 2023-12-20T11:28:01




#### Bump Test Response Delay. Actuator ID 330 2023-12-20T11:44:16




## Bump Test Response Delay. Actuator ID 235 2023-12-21T11:56:19




## Bump Test Response Delay. Actuator ID 238 2023-12-22T09:20:47




### Bump Test Response Delay. Actuator ID 330 2023-12-22T09:35:51




## Bump Test Response Delay. Actuator ID 418 2023-12-22T09:46:03




## Bump Test Response Delay. Actuator ID 109 2023-12-22T17:17:57




## Bump Test Response Delay. Actuator ID 238 2023-12-22T17:45:52




## Bump Test Response Delay. Actuator ID 410 2023-12-22T18:07:39




## Bump Test Response Delay. Actuator ID 108 2023-12-22T20:11:05




## Bump Test Response Delay. Actuator ID 108 2023-12-22T20:11:05




# Bump Test Response Delay. Actuator ID 310 2023-12-22T20:11:39




# Bump Test Response Delay. Actuator ID 310 2023-12-22T20:11:39




# Bump Test Response Delay. Actuator ID 422 2023-12-22T20:12:14




# Bump Test Response Delay. Actuator ID 108 2023-12-22T20:15:21




# Bump Test Response Delay. Actuator ID 108 2023-12-22T20:15:21




# Bump Test Response Delay. Actuator ID 310 2023-12-22T20:15:56




# Bump Test Response Delay. Actuator ID 310 2023-12-22T20:15:56




## Bump Test Response Delay. Actuator ID 422 2023-12-22T20:16:30




#### Bump Test Response Delay. Actuator ID 105 2023-12-23T02:44:51




## Bump Test Response Delay. Actuator ID 105 2023-12-23T02:46:14




### Bump Test Response Delay. Actuator ID 105 2023-12-26T17:13:29




### Bump Test Response Delay. Actuator ID 105 2023-12-26T17:14:16




### Bump Test Response Delay. Actuator ID 105 2023-12-26T17:14:16




### Bump Test Response Delay. Actuator ID 105 2023-12-27T19:43:00




### Bump Test Response Delay. Actuator ID 105 2023-12-27T19:43:00




# Bump Test Response Delay. Actuator ID 330 2023-12-27T20:27:07




# Bump Test Response Delay. Actuator ID 330 2023-12-27T20:49:01




# Bump Test Response Delay. Actuator ID 330 2023-12-27T20:52:59




# Bump Test Response Delay. Actuator ID 330 2023-12-27T20:55:13




# Bump Test Response Delay. Actuator ID 330 2023-12-27T20:55:42




## Bump Test Response Delay. Actuator ID 105 2023-12-28T05:31:12




### Bump Test Response Delay. Actuator ID 105 2023-12-28T05:31:12




## Bump Test Response Delay. Actuator ID 105 2023-12-29T05:19:18




### Bump Test Response Delay. Actuator ID 105 2023-12-29T05:19:18




## Bump Test Response Delay. Actuator ID 410 2023-12-29T06:10:09




### Bump Test Response Delay. Actuator ID 105 2023-12-30T05:08:41




### Bump Test Response Delay. Actuator ID 105 2023-12-30T05:08:41




### Bump Test Response Delay. Actuator ID 235 2023-12-30T05:36:52




## Bump Test Response Delay. Actuator ID 330 2024-01-03T10:32:33




# Bump Test Response Delay. Actuator ID 410 2024-01-03T10:39:22




#### Bump Test Response Delay. Actuator ID 330 2024-01-03T17:39:44




#### Bump Test Response Delay. Actuator ID 330 2024-01-03T17:39:44




# Bump Test Response Delay. Actuator ID 410 2024-01-03T17:40:36




# Bump Test Response Delay. Actuator ID 410 2024-01-03T17:41:06




## Bump Test Response Delay. Actuator ID 410 2024-01-03T17:41:40




# Bump Test Response Delay. Actuator ID 410 2024-01-03T17:49:57




# Bump Test Response Delay. Actuator ID 410 2024-01-03T17:50:37




# Bump Test Response Delay. Actuator ID 410 2024-01-03T17:51:43




# Bump Test Response Delay. Actuator ID 410 2024-01-03T17:55:07




# Bump Test Response Delay. Actuator ID 410 2024-01-03T17:57:32




## Bump Test Response Delay. Actuator ID 330 2024-01-03T18:08:47




# Bump Test Response Delay. Actuator ID 410 2024-01-03T18:09:27




# Bump Test Response Delay. Actuator ID 410 2024-01-04T10:59:33





### Bump Test Response Delay. Actuator ID 235 2024-01-05T03:47:52





#### Bump Test Response Delay. Actuator ID 235 2024-01-05T03:53:08
























































































# Bump Test Response Delay. Actuator ID 238 2024-01-09T05:44:50
































# Bump Test Response Delay. Actuator ID 330 2024-01-10T06:43:01







# Bump Test Response Delay. Actuator ID 410 2024-01-11T03:32:16




## Bump Test Response Delay. Actuator ID 218 2024-01-12T05:33:05



# Bump Test Response Delay. Actuator ID 238 2024-01-12T05:41:51



# Bump Test Response Delay. Actuator ID 410 2024-01-12T06:03:19



# Bump Test Response Delay. Actuator ID 104 2024-01-12T23:51:43

