Section	Synopsis	Reference
406.4(G)	Added section covering protection of floor receptacles using relocated requirements from former 406.9(D).	FR-7667, FR-7668, SR-8147
406.6(D)	Revised to address faceplates with integral night lights and USB chargers and added a new exception covering spring-tensioned contact connections of faceplates.	FR-7564, SR-8143
406.7	Revised to delete sentence stating that attachment plugs, cord connectors, and flanged surface devices shall not be reconditioned, as it is covered by new 406.2	SCR-90
406.9(A)	Revised to require WR ratings for other receptacles.	FR-7598
406.9(A)	Revised to require hinged covers of outlet box hoods to open at least 90 degrees, or fully open if not designed to open 90 degrees, after installation.	SR-8150
406.9(B)	Revised to require other receptacles installed in a wet location to be weather-resistant type and to require hinged covers of outlet box hoods to open at least 90 degrees, or fully open if not designed to open 90 degrees, after installation.	FR-7598, SR-8150
406.9(C)	Revised to clarify receptacle installations within a bathtub and shower space and to add exceptions pertaining to hydromassage bathtub receptacles and weight supporting ceiling receptacles (WSCR).	FR-7578, FR-7608, SR-8152
406.12(1)	Revised list item (1) to include tamper-resistant receptacle requirements in all dwellings, boathouses, mobile homes, and manufactured homes.	FR-7663
406.12(5)	Revised list item (5) to add the term "within" for clarity of what areas require tamper-resistant receptacles and to add lobbies, corridors, waiting spaces, and spaces used for patient sleeping.	FR-7665
406.12(6)	Revised to list item (6) add fitness centers and to clarify that gymnasiums include those within both educational and commercial facilities.	FR-7666
406.12(8) and (9)	Revised list items (8) and 9 to include residential care facilities, rehabilitation facilities, group homes, foster care, nursing homes, and psychiatric hospitals.	FR-7669
406.12(10)	Added list item (10) covering agricultural buildings accessible to the public and any common areas.	FR-7664
406.12, Exception	Revised Item (3) of Exception to (1) through (10) to add clarity.	FR-7662
408.2	Relocated former 408.8 covering reconditioned equipment, revised to remove duplicative requirements with 110.21(A)(2), added the term "corrosive influences", and added "switchboards" to correct inadvertent omission from the 2020 edition.	FR-7951, SCR-78
408.4	Revised for clarity and to remove any potential conflict with the defined term and added "physical location" to the source of supply marking requirement.	FR-7895, SR-7861
408.36(D)	Revised to replace the term "panel" with "panelboard."	FR-7891
408.38	Revised to add an evaluation requirement on systems with fault currents above 10,000 amperes.	FR-7950
108.43	Revised to include mounting of panelboards in the face-down position.	FR-7944
109.3	Deleted Table 409.3 due to redundancy with 90.3.	SR-7662
409.60	Revised section for clarity around grounding and bonding of industrial control panels.	FR-8056, SR-7664
409.70	Added section covering surge protection.	FR-8053, SR-7680
409.102	Revised section title to "Busbars" as that is the only topic addressed in the requirements, with no requirements pertaining to conductors.	FR-8057
409.110	Revised to require permanent markings that are visible after installation, including clarification as to what markings are required to be installed inside and outside of the enclosure.	FR-8058, SR-7742
410.2	Relocated former 410.7 covering reconditioned equipment and revised to add ballasts, LED drivers, and lamps as equipment that cannot be reconditioned.	FR-7504, SCR-79
410.10(D)(1)	Revised to add luminaires (light kits) connected to paddle fans	FR-7505
410.10(F)	Revised to add "where subject to physical damage" and to add exception that recognizes additional protection provided by concrete slab.	FR-7656, SR-8165
410.16	Revised to add text and figure for clothes closet storage space that was formerly a part of the definition that was relocated to Article 100.	SR-8166