



# **Aviation Investigation Final Report**

Location: Glennallen, Alaska Accident Number: ANC23LA018

Date & Time: January 13, 2023, 12:01 Local Registration: N5373Y

Aircraft: Piper PA-18-180 Aircraft Damage: Substantial

**Defining Event:** Collision with terr/obj (non-CFIT) **Injuries:** 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot reported that, before landing his wheel/ski-equipped airplane at a snow-covered airstrip, he elected to "drag" the site, which involved doing a series of touch-and-go landings to determine the snow conditions before doing a full stop landing. He said that after completing two successful drags on the untouched snow, during the third, he inadvertently allowed the airspeed to decay, and he was unable to get airborne again. The airplane subsequently passed the end of the airstrip and impacted a snow-covered gravel berm. The airplane sustained substantial damage to the left wing and fuselage. The pilot reported that there were no preaccident mechanical malfunctions or anomalies that would have precluded normal operation.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain airspeed during a drag maneuver, which resulted in an overrun and subsequent impact with terrain.

## Findings

Aircraft	Airspeed - Not attained/maintained
Personnel issues	Decision making/judgment - Pilot

Page 2 of 5 ANC23LA018

## **Factual Information**

### **History of Flight**

Landing	Collision with terr/obj (non-CFIT) (Defining event)

### **Pilot Information**

Certificate:	Private	Age:	69,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	February 3, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	August 9, 2021
Flight Time:	2060 hours (Total, all aircraft), 2060 hours (Total, this make and model), 2060 hours (Pilot In Command, all aircraft), 10 hours (Last 90 days, all aircraft), 0 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Piper	Registration:	N5373Y
Model/Series:	PA-18-180	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18-8140
Landing Gear Type:	Tailwheel; Ski/wheel	Seats:	2
Date/Type of Last Inspection:	December 16, 2022 Annual	Certified Max Gross Wt.:	2000 lbs
Time Since Last Inspection:	12 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	4688 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	C91 installed, activated, aided in locating accident	Engine Model/Series:	O-360-A2A
Registered Owner:	On file	Rated Power:	180 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 ANC23LA018

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	77 Nautical Miles
Observation Time:	09:00 Local	Direction from Accident Site:	62°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	None / None
Wind Direction:		Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.92 inches Hg	Temperature/Dew Point:	-12.2°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Wasilla , AK (5L6)	Type of Flight Plan Filed:	None
Destination:	Eureka, AK (3AK1)	Type of Clearance:	None
Departure Time:	10:30 Local	Type of Airspace:	Class G

## Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	62.00667,-147.30638

Page 4 of 5 ANC23LA018

#### **Administrative Information**

Investigator In Charge (IIC):	Johnson, Clinton
Additional Participating Persons:	Tony Bockelman; Federal Aviation Administration; Wasilla, AK
Original Publish Date:	April 27, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=106664

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC23LA018