



# **Aviation Investigation Final Report**

Location: Guthrie, Oklahoma Accident Number: CEN23LA117

Date & Time: February 20, 2023, 11:00 Local Registration: N25342

Aircraft: Luscombe 8A Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

The student pilot reported that, while rolling out on landing, the airplane suddenly veered to the right causing the nose to turn to the left. The student pilot attempted to correct with opposite rudder; however, the airplane exited the left side of the runway, proceeded down a terrace, and nosed over, which resulted in substantial damage to the vertical stabilizer. The student pilot reported that there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation. At the time of the accident, the student pilot was landing the airplane on runway 34 with wind from 300° at 6 knots.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The student pilot's failure to maintain directional control during the landing roll.

#### **Findings**

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

## **Factual Information**

### **History of Flight**

Landing	Loss of control on ground (Defining event)	
Landing-landing roll	Attempted remediation/recovery	
Landing-landing roll	Runway excursion	
Landing-landing roll	Nose over/nose down	

#### **Pilot Information**

Certificate:	Student	Age:	65,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	March 29, 2022
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 112 hours (Total, all aircraft), 98 hours (Total, this make and model), 53 hours (Pilot In Command, all aircraft)		

Page 2 of 5 CEN23LA117

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Luscombe	Registration:	N25342
Model/Series:	8A	Aircraft Category:	Airplane
Year of Manufacture:	1940	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	1218
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	December 3, 2022 Annual	Certified Max Gross Wt.:	1310 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	854.3 Hrs	Engine Manufacturer:	Continental
ELT:	C91 installed, not activated	Engine Model/Series:	C-85-12
Registered Owner:	HAPPY HOUR LUSCOMBE LLC	Rated Power:	85 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KGOK,1065 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	10:53 Local	Direction from Accident Site:	51°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	300°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.82 inches Hg	Temperature/Dew Point:	12°C / 3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Guthrie, OK	Type of Flight Plan Filed:	None
Destination:	Guthrie, OK	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Page 3 of 5 CEN23LA117

### **Airport Information**

Airport:	GUTHRIE-EDMOND RGNL GOK	Runway Surface Type:	Concrete
Airport Elevation:	1069 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	34	IFR Approach:	None
Runway Length/Width:	5001 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

### Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	35.850679,-97.415998(est)

Page 4 of 5 CEN23LA117

#### **Administrative Information**

Investigator In Charge (IIC):	Finne, Andrew
Additional Participating Persons:	Schreiber, Laurence; FAA-FSDO; Oklahoma City, OK
Original Publish Date:	March 30, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=106765

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CEN23LA117