

Power ON/OFF Sequences and Power-On-Reset (POR) on A2100-A/B

Application Notes

Version 1.0



Revision History

Rev.	Date	Description
1.0	05-18-11	First release
	mm-dd-yy	



Disclaimer

THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF MAESTRO WIRELESS SOLUTIONS LIMITED. IT MAY NOT BE COPIED OR TRANSMITTED BY ANY MEANS, PASSED TO OTHERS, OR STORED IN ANY RETRIEVAL SYSTEM OR MEDIA, WITHOUT PRIOR CONSENT OF MAESTRO OR ITS AUTHORIZED AGENTS.

THE INFORMATION IN THIS DOCUMENT IS, TO THE BEST OF OUR KNOWLEDGE, ENTIRELY CORRECT. HOWEVER, MAESTRO CAN NEITHER ACCEPT LIABILITY FOR ANY INACCURACIES, OR THE CONSEQUENCES THEREOF, NOR FOR ANY LIABILITY ARISING FROM THE USE OR APPLICATION OF ANY CIRCUIT, PRODUCT, OR EXAMPLE SHOWN IN THE DOCUMENT.

THE PRODUCT (HARD- AND SOFTWARE) DESCRIBED IN THIS DOCUMENTATION IS NOT AUTHORIZED FOR USE IN LIFE SUPPORT DEVICES OR SYSTEMS WITHOUT THE EXPRESS WRITTEN APPROVAL OF MAESTRO.

THIS DOCUMENT MAY PROVIDE LINKS TO OTHER WORLD WIDE WEB SITES OR RESOURCES. BECAUSE MAESTRO HAS NO CONTROL OVER SUCH SITES AND RESOURCES, MAESTRO SHALL NOT BE RESPONSIBLE FOR THE AVAILABILITY OF SUCH EXTERNAL SITES OR RESOURCES, AND DOES NOT ENDORSE AND IS NOT RESPONSIBLE OR LIABLE FOR ANY CONTENT, ADVERTISING, PRODUCTS, OR OTHER MATERIALS ON OR AVAILABLE FROM SUCH SITES OR RESOURCES. MAESTRO SHALL NOT BE RESPONSIBLE OR LIABLE, DIRECTLY OR INDIRECTLY, FOR ANY DAMAGE OR LOSS CAUSED OR ALLEGED TO BE CAUSED BY OR IN CONNECTION WITH USE OF OR RELIANCE ON ANY SUCH CONTENT, GOODS OR SERVICES AVAILABLE ON OR THROUGH ANY SUCH SITE OR RESOURCE.

MAESTRO RESERVES THE RIGHT TO CHANGE, MODIFY, OR IMPROVE THIS DOCUMENT OR THE PRODUCT DESCRIBED HEREIN, AS SEEN FIT BY MAESTRO WITHOUT FURTHER NOTICE.



Table of Contents

1 Introduction	5
2 Power sequence	5
2.1Power on sequence	
2.2 Power off sequence	
3 External POR implementation on A2100-A/B	
4 Related Information	
4.1 Contact	
5.Reference	



1 Introduction

Orderly shut-down process to properly stop internal operation and complete any write of critical data to internal RAM or Flash memory of A2100-A/B is recommended. Proper power ON and OFF sequences will be presented on section 2 of this application notes.

Although the probability of an exact coincidence of a power decrease during a flash data write or sector erase is very low, it is not zero. Abrupt removal or drop of main power while the system is running has risks ranging from fatal corruption of flash memory code area to minor impact on TTFF from lost data. Therefore, an additional external POR device is connected to nRST of A2100-A/B for monitoring the sudden main power drop is proposed on section 3.

2 Power sequence

2.1Power on sequence

Power On Sequence




Fig 1. Power ON Sequence on A2100-A/B

Parameter	Symbol	Min	Тур	Max	Unit
Vcc to nRST	tCR	50			ms
nRST to ON_OFF	tRO	0	10		ms
ON_OFF pulse	tON_OFF	150	200		ms



2.2 Power off sequence




Fig 2. Power OFF Sequence on A2100-A/B

Parameter	Symbol	Min	Тур	Max	Unit
ON_OFF pulse	tON_OFF	150	200		ms
ON_OFF to VCC	tOV	0	50		ms

3 External POR Implementation on A2100-A/B

Abrupt or uncontrolled removal of power while the A2100-A/B is operating carries the risk of data corruption when writes to internal memory are occurring or when sectors of flash memory are being erased. The consequences of memory corruption range from longer TTFF to complete system failure. The problem can be avoided by monitoring A2100-A/B supply using an external POR device.




Fig 3. Recommended POR circuitry for A2100-A






Fig 4. Recommended POR circuitry for A2100-B

We strongly recommend simulating and testing the POR circuitry in your product design before implementing to the final product application. In any case it is the responsibility of the designer to test and verify the implementation.



4 Related Information

4.1 Contact

This manual is created with due diligence. We hope that it will be helpful to the user to get the most out of the GPS module.

Inputs about errors or mistakable verbalizations and comments or suggestions to Maestro Wireless for further improvement are highly appreciated.

Maestro Wireless Solutions Limited

Unit 3603-09,36/F., 118 connuaught Road West,HK

Main Line: (852) 28690688

Fax: (852)25254701

<u>support-gps@maestro-wireless.com</u> www.maestro-wireless.com

5.Reference

[1] CSR Application Notes - GSD4e Supply Voltage Control and Sequencing Application notes (CS-210069-AN-2)

[2] Data sheet of MAX809SEUR+T

URL: http://datasheets.maxim-ic.com/en/ds/MAX803-MAX810Z.pdf

[3] Data sheet of R3111N162C-TR-FE

URL: http://www.ricoh.com/LSI/product_power/vd/r3111x/r3111x-e.pdf