



Sizes in mm. Tolerances to ISO 2768-mK unless stated.
Take any size not shown from the STEP file of the same number.
Break sharp edges 0.2 mm.
Holes for screws are clearance holes, unless a note taps them.
Tap the 6.8 mm holes M8, for the feet. Tapped: 4 x M3 x 6 deep, 4 x M6 x 10 deep.

Part Base plate		
Drawing OPTIMA-S01	Quantity 1	Scale 1:5
Material 6061-T6 aluminium	Finish Black anodized	
OPTIMA microscope. Sizes in mm. First-angle projection.		