General

top

Basically, the TM100-2/2A is a very nice floppy disk drive. I use it with my DREM and FLUXCOPY in conjunction with hard-sectored floppies. So far I have had only good experiences. Especially the drives that are still good and functional today are excellent in my opinion.

Technical Specifications

MODEL TM-100-	−1	−2	−3	−4
Recording	Single Side	Double Side	Single Side	Double Side
TPI	48	48	96/100	96/100
Track/Diskette	40	80	80	160
RPM	300	300	300	300
Capacity (unformatted)				
Double Density	250KB	500KB	500KB	1000KB
Access Time				
Track to Track	5 ms	5ms	3ms	3ms
Average	75ms	75ms	90ms	90ms
Head Settle Time	15ms	15ms	15ms	15ms
Head Load Time	-0-	-0-	-0-	-0-
Power up Delay	1 sec	1 sec	1 sec	1 sec
Start Time	250ms	250ms	250ms	250ms
Stop Time	150ms	150ms	150ms	150ms
Mechanical Dimensions				
Width	5.75	5.75	5.75	5.75
Height	3.25	3.25	3.25	3.25
Depth	8.0	8.0	8.0	8.0
DC Voltage Requirements	+12/+5	+12/+5	+12/+5	+12/+5
Current Requirements	900ma/ 600ma	900ma/ 600ma	900ma/ 600ma	900ma/ 600ma
Reliability				
MTBF-Typical Usage	8000HR	8000HR	8000HR	8000HR
PM	None	None	None	None
MTTR	.5HR	.5HR	.5HR	.5HR
Error Rates				
Soft Read	$1-10^{9}$	$1-10^{9}$	$1-10^{9}$	$1-10^{9}$
Hard Read	$1-10^{12}$	$1-10^{12}$	$1-10^{12}$	$1-10^{12}$
Media Life	4×10^{6}	4×10^{6}	4×10^{6}	4×10^{6}

Tandon TM100 technical specifications
(Source: Brochure Tandom TM100 Series)

Alignment

top

Among the links below you will find two good pages on this topic by Terry Stewart (here is a copy). I have made the experience that sometimes only the track 0 is not set correctly. And you only have to turn one screw. This is actually quite simple. So I got two drives working again within 30 minutes.

Information

top

Brochures

- Tandon TM100 Series (Feb 1980)

Manuals

- TM100 users manual (1984)
- TM100 service manual (1983)
- Sams Computerfacts, Tandon TM-100-2/2A (02/1986)

External Links

top

- Minuszerodegrees - Tandon TM100-2 - Known Problems/Issues
- Terry Stewart's (Tezza's) Projects and Articles (Blog)
  - Adjusting the radial alignment a Tandon TM100-2A drive without an alignment disk
  - Tandon TM100-2A disk drive alignment on an IBM-PC (5150)
  - Fixing a Tandon TM100 drive on a Kaypro II

© 2023 Thomas Brase