
Drive-select setting in the
IBM PC and IBM XT.




This is a resistor network.

In the TM100-2, it is performing the fu

In the TM100-2, the type of resistor ne

As fitted to the IBM PC and IBM XT, th



8 resistors,
each of 150 oh

The part in the photo is made by Bourns,
and the part number printed on it is "16-1-151".

Some replacements:

Make: BI	Make: Bourns	Mak
Model: 898-3-R150	Model: 4116R-1-151	Mod