Manual Error: too low
Automated Error: Low signal: all GIC values within +/- 4 A;
Excessive pre-storm noise: std before (0.0476 A) > 1/4 * std after (0.0902 A)