

Sensor A1,  $T = 20\text{ C}$ ,  $v_{\text{over}} = 7\text{ V}$  - Decreasing and disappearing fluctuating,  $400 < L < 1000$

