
Sensor A1, T = 20 C, v_over = 7 V - luminosity vs phase - order 10^1
luminosity
Detected measurement
Forced measurement
spot 11
spot 16
spot 20
spot 21
spot 25
spot 26
120
100
80
60
40
20
0
−20
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_25h
annealing phase