
Sensor A1, T = 20 C, v_over = 7 V - luminosity vs phase - order 10^1
luminosity
Detected measurement
Forced measurement
spot 29
spot 39
spot 40
spot 51
spot 52
spot 60
120
100
80
60
40
20
0
–20
–40
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_225h
annealing phase