
Sensor A1, T = 20 C, v_over = 7 V - luminosity vs phase - order 10^1
luminosity
120
100
80
60
40
20
0
−20
−40
Detected measurement
Forced measurement
spot 90
spot 94
spot 96
spot 97
spot 98
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_225h
annealing phase