
Sensor A1, T = 20 C, v_over = 7 V - luminosity vs phase - order 10^2
luminosity
900
800
700
600
500
400
300
200
100
0
Detected measurement
Forced measurement
spot 1
spot 2
spot 4
spot 5
spot 8
spot 9
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_225h
annealing phase