
Sensor A1, T = 20 C, v_over = 7 V - luminosity vs phase - order 10^2
luminosity
Detected measurement
Forced measurement
spot 10
spot 12
spot 14
spot 15
spot 17
spot 19
500
400
300
200
100
0
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_225h
annealing phase