
Sensor A1, T = 20 C, v_over = 7 V - luminosity vs phase - order 10^2
luminosity
800
700
600
500
400
300
200
100
0
Detected measurement
Forced measurement
spot 61
spot 65
spot 66
spot 69
spot 70
spot 71
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_225h
annealing phase