
Sensor A1, T = 20 C, v_over = 7 V - luminosity vs phase - order 10^3
luminosity
6000
5000
4000
3000
2000
1000
Detected measurement
Forced measurement
spot 73
spot 77
spot 85
spot 87
spot 88
spot 91
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_225h
annealing phase