
Sensor B1, T = 20 C, v_over = 5 V - luminosity vs phase - order 10^2
luminosity
Detected measurement
Forced measurement
spot 7
spot 8
spot 10
spot 12
spot 13
spot 15
450
400
350
300
250
200
150
100
50
0
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_225h
annealing phase