
Sensor B1, T = 20 C, v_over = 5 V - luminosity vs phase - order 10^2
luminosity
1000
800
600
400
200
0
Detected measurement
Forced measurement
spot 27
spot 28
spot 31
spot 32
spot 33
spot 35
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_225h
annealing phase