
Sensor B1, T = 20 C, v_over = 5 V - luminosity vs phase - order 10^2
luminosity
1200
1000
800
600
400
200
0
Detected measurement
Forced measurement
spot 37
spot 38
spot 39
spot 40
spot 43
spot 44
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_225h
annealing phase