
Sensor B1, T = 20 C, v_over = 5 V - luminosity vs phase - order 10^2
luminosity
Detected measurement
Forced measurement
spot 46
spot 47
spot 48
spot 52
spot 54
spot 55
600
500
400
300
200
100
0
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_225h
annealing phase