
Sensor B1, T = 20 C, v_over = 5 V - luminosity vs phase - order 10^2
luminosity
800
700
600
500
400
300
200
100
0
−100
Detected measurement
Forced measurement
spot 86
spot 88
spot 91
spot 92
spot 93
spot 94
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_225h
annealing phase