
Sensor B1, T = 20 C, v_over = 5 V - luminosity vs phase - order 10^3
luminosity
10000
8000
6000
4000
2000
0
Detected measurement
Forced measurement
spot 0
spot 9
spot 16
spot 23
spot 25
spot 26
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_225h
annealing phase