
Sensor B1, T = 20 C, v_over = 5 V - luminosity vs phase - order 10^3
luminosity
7000
6000
5000
4000
3000
2000
1000
0
Detected measurement
Forced measurement
spot 114
spot 115
spot 117
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_225h
annealing phase