
Sensor B1, T = 20 C, v_over = 5 V - luminosity vs phase - order 10^4
×10^3
luminosity
100
80
60
40
20
Detected measurement
Forced measurement
spot 11
spot 14
spot 30
spot 63
spot 65
bef_ann
ann_75C_5h
ann_75C_25h
ann_100C_5h
ann_100C_25h
ann_125C_5h
ann_125C_25h
ann_150C_5h
ann_150C_25h
ann_150C_225h
annealing phase