

Figure 10 is a plot showing the relative uncertainty of the R16/R24 ratio for different annealing phases. The y-axis represents the relative uncertainty, ranging from 1.0 to 2.6. The x-axis lists various annealing phases: bef\_ann, ann\_75C\_5h, ann\_75C\_25h, ann\_100C\_5h, ann\_100C\_25h, ann\_125C\_5h, ann\_125C\_25h, ann\_150C\_5h, and ann\_150C\_25h. Two data series are shown: 'Statistical uncertainty' (black error bars) and 'Systematic uncertainty (R16/R24)' (purple error bars). The plot shows that the relative uncertainty is highest for the 'bef\_ann' phase and decreases as the annealing phase progresses, with the 'ann\_150C\_25h' phase showing the lowest uncertainty.

Figure 10 is a plot showing the statistical and systematic uncertainties of the R16/R24 ratio for different annealing phases. The y-axis represents the ratio, ranging from 2.0 to 4.0. The x-axis lists various annealing phases: bet\_ann, ann\_75C\_5h, ann\_75C\_25h, ann\_100C\_5h, ann\_100C\_25h, ann\_125C\_5h, ann\_125C\_25h, ann\_150C\_5h, and ann\_150C\_25h. For each phase, a vertical black line with a crossbar indicates the statistical uncertainty, and a horizontal purple line indicates the systematic uncertainty (R16/R24). The statistical uncertainty is generally larger for the first four phases and smaller for the last five phases. The systematic uncertainty is consistently around 2.8 for all phases.