

Sensor A1, T = 20 C -  $L(\text{ann\_125C\_25h}) / L(\text{before\_annealing})$

