


Sensor A1 - Mean luminosity vs annealing phase, $T = 20^{\circ}\text{C}$, $v_{\text{over}} = 5 \text{ V}$

Mean luminosity



Annealing time