

Sensor B1 - Dark Current vs temperature for all annealing phases

Dark Current (A)

