

Sensor B1, $T = 20\text{ C}$, $v_{\text{over}} = 5\text{ V}$ - Decreasing and disappearing fluctuating, $400 < L < 1000$

