Italy NSC
Parts & Services
305-26 db

Spett.li: Riparatori Autorizzati ABARTH
Riparatori Autorizzati ALFA ROMEO
Riparatori Autorizzati FIAT
Riparatori Autorizzati FIAT PROFESSIONAL
Riparatori Autorizzati LANCIA

Torino, 04 settembre 2026

## CHIUSURA CAMPAGNE

Vi segnaliamo che è stata fissata la chiusura tecnica programmata al 30 settembre 2026, delle seguenti campagne:

| Campaign | Campaign Type | Brand Description | Date Launch | Campaign Description |
|---|---|---|---|---|
| 6874 | RSU - Rapid Service Update | Abarth | 2024-09 | FIAT 600 BEV - EVCU Software Update |
| 6887 | RSU - Rapid Service Update | Abarth | 2024-08 | ABARTH 500 BEV - Door Glass Seal |
| 6895 | RSU - Rapid Service Update | Abarth | 2024-09 | ABARTH 600 BEV - Right Lock Verification and Replacement |
| 6842 | RSU - Rapid Service Update | Alfa Romeo | 2024-07 | Alfa Romeo Tonale - Software Update |
| 6843 | RSU - Rapid Service Update | Alfa Romeo | 2024-09 | Alfa Romeo Tonale PHEV - AHCP, HCP and PCM Software Update |
| 6858 | RSU - Rapid Service Update | Alfa Romeo | 2024-09 | ALFA ROMEO GIULIA, STELVIO, TONALE TT - SGW Software Update |
| 6881 | RSU - Rapid Service Update | Alfa Romeo | 2024-09 | ALFA ROMEO JUNIOR - "SPECIALE" Badge Verification and Application |
| 6882 | RSU - Rapid Service Update | Alfa Romeo | 2024-09 | Alfa Romeo Stelvio - Front Wiper Blade Verification and Replacement |
| 6894 | RSU - Rapid Service Update | Alfa Romeo | 2024-09 | ALFA ROMEO JUNIOR - Right Lock Verification and Replacement |
| 6826 | RSU - Rapid Service Update | Fiat | 2024-07 | FIAT PRO SCUDO (K0) DOBLÒ (K9) - BCM Update and Variant Coding |
| 6829 | RSU - Rapid Service Update | Fiat | 2024-07 | FIAT DOBLÒ K9 - BCM Replacement and Configuration |
| 6830 | RSU - Rapid Service Update | Fiat | 2024-07 | FIAT DOBLÒ VAN K9 - BCM Replacement and Configuration |
| 6833 | RSU - Rapid Service Update | Fiat | 2024-08 | Fiat Scudo (K0) - IPC Software Update |

| | | | | |
|---|---|---|---|---|
| 6835 | RSU - Rapid Service Update | Fiat | 2024-07 | 500X, TIPO MCA - Oil Sump Sealant Verification and Replacement |
| 6836 | RSU - Rapid Service Update | Fiat | 2024-07 | FIORINO - Oil Sump Sealant Verification and Replacement |
| 6837 | RSU - Rapid Service Update | Fiat | 2024-07 | Fiat PRO Scudo (K0) - EPS Software Update |
| 6838 | RSU - Rapid Service Update | Fiat | 2024-07 | FIAT PRO DUCATO - Torque Converter Bolts Replacement |
| 6839 | RSU - Rapid Service Update | Fiat | 2024-07 | FIAT PRO Scudo BEV (K0) - EVCU Software Update |
| 6841 | RSU - Rapid Service Update | Fiat | 2024-08 | Fiat PRO Titano - Gearbox Breather Repair |
| 6855 | RSU - Rapid Service Update | Fiat | 2024-08 | FIAT PRO Doblò (K9) - EVCU Software Update |
| 6856 | RSU - Rapid Service Update | Fiat | 2024-07 | Fiat PRO Scudo (K0) - Trim Rework |
| 6857 | RSU - Rapid Service Update | Fiat | 2024-07 | FIAT 600 - BCM Calibration |
| 6860 | RSU - Rapid Service Update | Fiat | 2024-07 | FIAT PRO SCUDO (K0) - Body Sealing |
| 6861 | RSU - Rapid Service Update | Fiat | 2024-07 | Fiat PRO Ducato - Proximity Radar Calibration |
| 6864 | RSU - Rapid Service Update | Fiat | 2024-08 | Doblò (K9) - Fuel Damper Verification and Replacement |
| 6865 | RSU - Rapid Service Update | Fiat | 2024-08 | Doblò (K9) - Fuel Damper Verification and Replacement |
| 6868 | RSU - Rapid Service Update | Fiat | 2024-07 | FIAT 600 MHEV - Snap Ring Inspection and Repair |
| 6870 | RSU - Rapid Service Update | Fiat | 2024-07 | Fiat PRO Doblò (K0) – Sliding button Inspection and Repair |
| 6871 | RSU - Rapid Service Update | Fiat | 2024-08 | Fiat PRO Doblò (K9) - Exhaust Pipe Inspection and Repair |
| 6872 | RSU - Rapid Service Update | Fiat | 2024-08 | FIAT Doblò BEV (K9) - Reducer |
| 6874 | RSU - Rapid Service Update | Fiat | 2024-09 | FIAT 600 BEV - EVCU Software Update |
| 6875 | RSU - Rapid Service Update | Fiat | 2024-08 | FIAT PRO Doblò (K9) - EVCU Software Update |
| 6877 | RSU - Rapid Service Update | Fiat | 2024-08 | FIAT Doblò (K9) - Microphone Verification and Replacement |
| 6878 | RSU - Rapid Service Update | Fiat | 2024-08 | FIAT PRO Doblò (K9) - Microphone Verification and Replacement |
| 6884 | RSU - Rapid Service Update | Fiat | 2024-09 | Fiat PRO Ducato MCA - BCM Proxy Update |
| 6885 | RSU - Rapid Service Update | Fiat | 2024-08 | Fiat PRO Doblò (K9) - Front Strut Weld Restoration |
| 6886 | RSU - Rapid Service Update | Fiat | 2024-08 | FIAT 500 BEV - Door Glass Seal |
| 6892 | RSU - Rapid Service Update | Fiat | 2024-09 | Fiat PRO Scudo (K0) - Paint Inspection and Restoration |
| 6893 | RSU - Rapid Service Update | Fiat | 2024-09 | FIAT 600 - Right Lock Verification and Replacement |
| 6904 | RSU - Rapid Service Update | Fiat | 2024-09 | FIAT PRO SCUDO (K0) - Fuel Damper Replacement |
| 6845 | RSU - Rapid Service Update | Lancia | 2024-07 | LANCIA YPSILON - Various Software Updates |
| 6869 | RSU - Rapid Service Update | Lancia | 2024-07 | LANCIA YPSILON MHEV - Snap Ring Inspection and Repair |

| | | | | |
|---|---|---|---|---|
| 6873 | RSU - Rapid Service Update | Lancia | 2024-08 | LANCIA YPSILON BEV - Reducer |
| 6876 | RSU - Rapid Service Update | Lancia | 2024-08 | LANCIA YPSILON BEV - EVCU Software Update |

Segnaliamo pertanto che le richieste di rimborso, relative agli interventi eseguiti entro il termine della chiusura tecnica, potranno essere da Voi inoltrate entro e non oltre il 31 Dicembre 2026.

Vi ricordiamo inoltre che la data di chiusura va rigorosamente rispettata.

Cordiali Saluti

Italy NSC - Parts & Services
Technical & Warranty Manager
**V.Caiano**