Italy NSC
Parts & Services
361-26 db

Spett.li: Riparatori Autorizzati ABARTH
Riparatori Autorizzati ALFA ROMEO
Riparatori Autorizzati FIAT
Riparatori Autorizzati FIAT PROFESSIONAL
Riparatori Autorizzati LANCIA

Torino, 06 ottobre 2026

CHIUSURA CAMPAGNE

Vi segnaliamo che è stata fissata la chiusura tecnica programmata al 31 ottobre 2026, delle seguenti campagne:

Campaign	Campaign Type	Brand Description	Date Launch	Campaign Description
6924	SR Safety Recall	Abarth	2024-10	500e - HV Battery Replacement
6178	SERVICE	Abarth	2018-01	Mod. CINQUECENTO - RADIO VP2 SW UPDATE
6635	RSU - Rapid Service Update	Abarth	2023-05	500e - PEB Module Check and Replacement
6655	RSU - Rapid Service Update	Abarth	2023-07	500e - Radio Software Update
6672	RSU - Rapid Service Update	Abarth	2023-07	500e - Dashboard Trim Check and Replacement
8247	SERVICE	Alfa Romeo	2019-01	Mod. GIULIA - VEHICLE REGISTRATION DOCUMENT
6264	SERVICE	Alfa Romeo	2019-01	Mod. GIULIETTA - NON-CONFORMING ENGINE MOUNT
6154	SERVICE	Alfa Romeo	2017-09	Mod. GIULIA - DASHBOARD COMPARTMENT AND AMPLIFIER COVER
8236	SERVICE	Alfa Romeo	2019-04	Mod. GIULIA & STELVIO 2.0 GME Engine - ECM SOFTWARE UPDATE
6380	SERVICE	Alfa Romeo	2021-10	MOD STELVIO - FRONT PARKING SENSOR
6593	RSU - Rapid Service Update	Alfa Romeo	2023-03	Tonale - Steering Column Replacement
6590	RSU - Rapid Service Update	Alfa Romeo	2023-03	Stelvio - Driver Airbag Replacement
6566	RSU - Rapid Service Update	Alfa Romeo	2023-03	Giulia 2.2 RWD E6DS - Urea Pipe Check and Replacement
6609	RSU - Rapid Service Update	Alfa Romeo	2023-04	Stelvio - Q4 Badge Check and Removal
6656	RSU - Rapid Service Update	Alfa Romeo	2023-07	Tonale PHEV - Radio Software Update

6594	SR Safety Recall	Fiat	2023-03	Scudo - Left Steering Arm Nut Replacement
6209	SERVICE	Fiat	2018-01	Mod. 500 X - VIN Plate
6333	SERVICE	Fiat	2021-07	MOD. 500 BEV - NON-CONFORMING IBS
6491	SERVICE	Fiat	2022-01	Scudo - Bolt Torquing / Steering Rack Replacement
6572	RSU - Rapid Service Update	Fiat	2023-02	New Doblò - Hood Replacement
6589	RSU - Rapid Service Update	Fiat	2023-02	Panda - Proxy Update
6570	RSU - Rapid Service Update	Fiat	2023-02	500e - TBM Software Update
6577	RSU - Rapid Service Update	Fiat	2023-03	Scudo E - Traction Battery Check and Replacement
6598	RSU - Rapid Service Update	Fiat	2023-03	Panda VAN - Air Filter Check and Refit
6597	RSU - Rapid Service Update	Fiat	2023-03	Panda - Air Filter Check and Refit
6612	RSU - Rapid Service Update	Fiat	2023-04	Ducato - Engine Timing Check and Adjustment
6620	RSU - Rapid Service Update	Fiat	2023-04	Ducato - Key Set Replacement
6611	RSU - Rapid Service Update	Fiat	2023-04	Tipo - ECM Software Update
6632	RSU - Rapid Service Update	Fiat	2023-05	Panda - Rear Window Winder Handle Check and Repair
6639	RSU - Rapid Service Update	Fiat	2023-06	Scudo - Air Duct Fixing Check and Repair
6654	RSU - Rapid Service Update	Fiat	2023-06	Ducato BEV - Noise Filter Module Replacement
6588	RSU - Rapid Service Update	Fiat	2023-06	Doblò BEV - OBC Software Update
6595	RSU - Rapid Service Update	Fiat	2023-06	New Doblò - Starlock Check and Replacement
6638	RSU - Rapid Service Update	Fiat	2023-06	Scudo - Hinge Paint Check and Repair
6647	RSU - Rapid Service Update	Fiat	2023-07	Ulysse ICE/BEV - Windscreen Sealant Check and Repair
6660	RSU - Rapid Service Update	Fiat	2023-07	Ulysse - Climate Control Panel Replacement
6665	RSU - Rapid Service Update	Fiat	2023-07	500e - H.V. Electric Traction Module Replacement
6649	RSU - Rapid Service Update	Fiat	2023-07	Scudo ICE/BEV - Windscreen Sealant Check and Repair
6664	RSU - Rapid Service Update	Fiat	2023-07	500e - Dashboard Trim Check and Replacement
6674	RSU - Rapid Service Update	Fiat	2023-07	Scudo - Parking Brake Cable Tightening
6662	RSU - Rapid Service Update	Fiat	2023-07	Scudo - Front Left Hub Fixing Check and Repair
6659	RSU - Rapid Service Update	Fiat	2023-07	Scudo - BSI Software Update
6661	RSU - Rapid Service Update	Fiat	2023-07	Scudo, Scudo BEV - Climate Control Panel Replacement
6670	RSU - Rapid Service Update	Fiat	2023-07	500X, Tipo - Proxy Update

6658	RSU - Rapid Service Update	Fiat	2023-07	Ulysse - BSI Software Update
5847	SERVICE	Fiat	2014-11	Mod. CINQUECENTO - SOFT TOP
6013	SERVICE	Fiat	2016-05	Mod. DOBLÒ VAN 1.6 mjtd Engine - ENGINE CONTROL UNIT
6039	SERVICE	Fiat	2016-07	Mod. FIORINO 1.3 mjtd E6 Engine - ENGINE CONTROL UNIT
6047	SERVICE	Fiat	2016-07	Mod. 500 Riva - WHEEL COVER
6129	SERVICE	Fiat	2017-05	Mod. FIORINO - DPF TEMPERATURE SENSORS
6177	SERVICE	Fiat	2018-01	Mod. CINQUECENTO - RADIO VP2 SW UPDATE
6188	SERVICE	Fiat	2018-05	Mod. DOBLÒ CARGO - VGT PIPE AND BODY SCREW CONTACT
6293	SERVICE	Fiat	2020-05	Mod. DUCATO - NEW HOMOLOGATION PLATE
6300	SERVICE	Fiat	2020-09	Mod. CINQUECENTO - FRONT ELECTRICAL WIRING
6326	SERVICE	Fiat	2021-03	Mod. DUCATO - QUICK COUPLING ON RADIATOR HOSE
6355	SERVICE	Fiat	2021-10	MOD DUCATO - 10'' CLIMATE CONTROL RADIO
6394	SERVICE	Fiat	2021-11	MOD DUCATO BEV - NON-CONFORMING WIRING CONNECTION
6346	SERVICE	Fiat	2021-12	MOD DUCATO - BSM SW UPDATE
6419	SERVICE	Fiat	2022-02	MOD 500BEV - TBM SW UPDATE
6433	SERVICE	Fiat	2022-03	500BEV - COVER KIT / GASKETS / FIXINGS REPLACEMENT
6460	SERVICE	Fiat	2022-05	Instrument Cluster IPC Software Update
6493	SERVICE	Fiat	2022-07	500X, TIPO - TRANSMISSION SCREW TIGHTENING
6497	SERVICE	Fiat	2022-07	SCUDO - LEFT REAR SUSPENSION SWING ARM
6184	SERVICE	Lancia	2018-04	Mod. YPSILON GPL Engine - IRREGULAR IGNITION MOTOR MALFUNCTION

Segnaliamo pertanto che le richieste di rimborso, relative agli interventi eseguiti entro il termine della chiusura tecnica, potranno essere da Voi inoltrate entro e non oltre il 31 Gennaio 2027.

Vi ricordiamo inoltre che la data di chiusura va rigorosamente rispettata.

Cordiali Saluti

Italy NSC - Parts & Services
Technical & Warranty Manager
V.Caiano