



Fakultät Informatik

# From CAD Software to Slicer

## Workflow Optimization using Print Hints in 3MF Files for 3D Printing

Bachelorarbeit im Studiengang Medieninformatik

vorgelegt von

Luise Hartdegen

Matrikelnummer 364 2168

Erstgutachter: Prof. Dr. Ulrich von Zadow

Zweitgutachter: Prof. Dr. Timo Götzelmann

© 2025

Dieses Werk einschließlich seiner Teile ist **urheberrechtlich geschützt**. Jede Verwertung außerhalb der engen Grenzen des Urheberrechtsgesetzes ist ohne Zustimmung des Autors unzulässig und strafbar. Das gilt insbesondere für Vervielfältigungen, Übersetzungen, Mikroverfilmungen sowie die Einspeicherung und Verarbeitung in elektronischen Systemen.

**Abstract**

**Kurzdarstellung**

//TODO

# Contents

|                                                              |           |
|--------------------------------------------------------------|-----------|
| <b>1. Introduction</b>                                       | <b>1</b>  |
| <b>2. Problem</b>                                            | <b>3</b>  |
| 2.1. Repetitive Steps in the Iterative Workflow              | 3         |
| 2.2. Negative Effects resulting from manual Repetitive Steps | 3         |
| 2.3. Usage of Presets                                        | 4         |
| <b>3. Background</b>                                         | <b>5</b>  |
| 3.1. State of the Art                                        | 5         |
| 3.2. Foundations                                             | 5         |
| <b>4. Method</b>                                             | <b>8</b>  |
| 4.1. Explored Possible Solutions                             | 8         |
| 4.2. Fusion Add-In                                           | 8         |
| 4.2.1. Script vs. Add-in                                     | 8         |
| 4.2.2. Python vs. C++                                        | 9         |
| 4.3. if necessary: changes to 3MF File Format                | 9         |
| 4.4. slicer changes                                          | 9         |
| 4.5. Implementation Design                                   | 9         |
| <b>5. Results</b>                                            | <b>10</b> |
| <b>6. Conclusion</b>                                         | <b>11</b> |
| 6.1. Outlook                                                 | 11        |
| 6.2. Summary                                                 | 11        |
| <b>A. Supplemental Information</b>                           | <b>12</b> |
| <b>List of Figures</b>                                       | <b>14</b> |
| <b>List of Tables</b>                                        | <b>15</b> |
| <b>List of Listings</b>                                      | <b>16</b> |
| <b>Bibliography</b>                                          | <b>17</b> |

# Chapter 1.

## Introduction

It is one of the clearest paradoxes of modern work that computer-based systems designed to reduce task complexity and cognitive workload actually often impose even greater demands and stresses on the very individuals they are supposed to be helping.[?, p. 222]

When designing a model for 3D printing, the process frequently follows a certain set of iterative steps. After the ideation phase, the design engineer first creates the model using CAD software, imports the file (e.g. STL, 3MF) to a slicer software, sets the necessary parameters and finally starts printing. They evaluate the result for design flaws or areas of improvement, leading to model revisions and thereby reinitiating the workflow as pictured in figure 2.1. Throughout the iterations, some printing parameters will be tweaked but overall you want to keep them consistent to have a reliable comparison. Despite automation and optimization having been a prevalent topic in the software developer community for years, setting the parameters is generally a manual step. Hence, the design engineer has to remember their settings or save them some other way, possibly by writing them down meticulously or taking screenshots.

With access to printers in public institutions becoming easier and the growing popularity of 3D printing not only within the *maker* community but in casual users as well, HCI needs to focus on streamlining error-prone workflows like the one described above[1]. “[C]urrent tools that focus on supporting only one aspect of the workflow (e.g. , only modelling or only printing) may be less useful for casual makers and there is opportunity in HCI research to innovate on design tools that take into account the interdependencies within the 3D printing workflow”[1, p. 385]

This thesis focuses on the communication between CAD software and slicer, with a particular focus on proving the feasibility of ‘print hints’. The goal is to streamline the iterative design workflow by reducing the need to repeatedly configure the same printing parameters in each iteration, therefore lowering cognitive workload for design engineers. The approach as currently planned contains two core components: firstly, an improved export function within the CAD software *Autodesk Fusion*, e.g. to mark certain objects

as modifiers; and second, automatic handling of materials and these print hints within the open source slicer software called *OrcaSlicer*.

basic (HCI) aspects in which I want to improve the workflow (possibly to be referenced in the following texts) → what does it solve

- sharing files with slicer but not printer specific settings
- how it reduces cognitive workload in repetitive steps

---

“*makers*, a community of enthusiasts who focus on fabrication, invention and experience sharing, and who collaborate and learn in environments known as *makerspaces*”[1, p. 384]

“thousands of public institutions, such as schools, libraries, and universities are now setting up print centers or creative hubs for end users to make use of digital fabrication technologies”[1, p. 384]

“makerspaces that are often run by enthusiasts [...] attract engineers, entrepreneurs, inventors, hackers, craftsmen, and artists”[1, p. 384]

“casual makers serve as a proxy for what it will be like for the general public to use 3D printing”[1, p. 384]

“if HCI is going to be at the forefront of inventing new fabrication design tools and interfaces [...], we need to look beyond enthusiasts and understand the challenges and opportunities that exist in facilitating the interactions of casual makers with fabrication technology”[1, p. 384]

“current tools that focus on supporting only one aspect of the workflow (*e.g.* , only modelling or only printing) may be less useful for casual makers and there is opportunity in HCI research to innovate on design tools that take into account the interdependencies within the 3D printing workflow”[1, p. 385]

“while lowering the usability barriers of fabrication tools is important, it is perhaps even more important to weave-in expertise on best practices and troubleshooting tips within the walk-up-and-use tools used by casual makers to reduce their dependency on operators”[1, p. 385]

“opportunities that exist in building the next generation of inter-connected fabrication tools with features for supporting expertise sharing”[1, p. 385]

“enthusiasts and professional users—that is, they were trained or technically literate in fabrication”[1, p. 386]

## Chapter 2.

### Problem

what's the real world problem I am trying to solve? why is solving it important?

### 2.1. Repetitive Steps in the Iterative Workflow




Figure 2.1.: Iterative workflow in 3D printing highlighting the step to be optimized

### 2.2. Negative Effects resulting from manual Repetitive Steps

//TODO research cognitive workload / increased amount of errors due to necessary repetitive steps (podcast about to-do lists → air plane take off / landing checklists (yes, this is relevant))

some HCI foundational work if necessary

“If the user’s print failed or did not match their design intent, they would have to adjust either their model or print settings to correct the issue, often with the operator’s assistance”[1, p. 389]

## 2.3. Usage of Presets

do people (esp. beginners) use presets? if no, why and how would it make their life easier? is it even possible in community spaces like libraries and schools?

## Chapter 3.

### Background

#### 3.1. State of the Art

- current situation → workflow as is with specific, tangible examples; how do others solve this?
- related work if applicable

#### 3.2. Foundations

- what is CAD software?
- what is a slicer?

“Processing the 3D model occurred in specialized software known as a slicer (as it slices the model into layers for the printer), which allowed users to select print settings, such as layer height and print speed”[1, p. 389].

- 3MF File Format → why 3mf and not stl or other file formats?

##### 3.2.0.1. The 3MF specification

[3]

- “3MF Document markup has been designed in anticipation of the evolution of this specification. It also allows third parties to extend the markup. Extensions are a critical part of 3MF, and as such, this core specification is as narrow as possible.” [p. 8]
- 3MF = ZIP archive following the .ZIP File Format Specifications by PKWARE Inc. containing one or more 3D payloads



| Name             | Description                                                                                           | Required / Optional |
|------------------|-------------------------------------------------------------------------------------------------------|---------------------|
| 3D Model         | Contains the description of one or more 3D objects for manufacturing.                                 | Required            |
| Core Properties  | The OPC part that contains various document properties.                                               | Optional            |
| Object Thumbnail | Contains a small JPEG or PNG image that represents a 3D object in a 3D Model.                         | Optional            |
| 3D Texture       | Contains a texture used to apply color to a 3D object in the 3D Model part (available for extensions) | Optional            |
| PrintTicket      | Provides settings to be used when outputting the 3D object(s) in the 3D Model part.                   | Optional            |
| Custom Parts     | OPC parts that are associated with meta-data                                                          | Optional            |

Table 3.1.: Excerpt of 3MF document parts[3, p. 4]

- 3D payload = “complete collection of interdependent parts and relationships within a package” consisting of “a 3D object definition and its supporting files”
- 3MF document parts → table 3.1, figure 3.1

```
example.3mf
├── _rels/
├── [Content_Types].xml/
├── 3D/
│   ├── 3dmodel.model
│   └── Metadata/
│       └── thumbnail.png
```

Figure 3.1.: Typical internal structure of 3MF file as exported from *Autodesk Fusion*

- PrintTicket → seems to be OS specific, so probably not helpful but **TODO** investigate further
- most important: 3D Model Part = root of 3D payload → “contains definitions of one or more objects to be fabricated by 3D manufacturing processes”[3, p. 6] → contains resource definitions (objects, materials) and items to be build
  - there MUST be exactly one <model> element in a 3D Model part
  - a model must have two additional child elements: <resources> and <build>
  - <resources> element

- \* provides a set of definitions that can be drawn from to define a 3D object
  - \* root element of a library of constituent pieces of the overall 3D object definition → objects, properties, materials
  - \* ‘object resource’: 3d object that could be but will not be manufactured on its own
- <build> element
- \* provides a set of items that should actually be manufactured as part of the job
  - \* contains <item> elements = objects to be manufactured

## Chapter 4.

### Method

what's the solution(s) I came up with → sketching out different possibilities and why I chose the one I did

#### 4.1. Explored Possible Solutions

#### 4.2. Fusion Add-In

- what is CAD software
- a lil about their API: add-in vs. script, Python vs. C++
- why I chose to realise it as a Python add-in
- possibly different approaches if more than one way to solve it came up

As mentioned before, the software supports developers to create additional functionalities by providing an extensive API and the option to create either an add-in or a script directly from within Fusion's UI. Using this, Fusion sets up the project structure as well as some example code to make it easier to get started especially for beginners. Fusion runs natively on Python but offers to create the add-in or script either in Python or in C++.

##### 4.2.1. Script vs. Add-in

[2]

- **Run on Startup** – This setting is add-in-specific and indicates if the add-in should be run automatically when Fusion is started. Most add-ins will want to take advantage of this capability so the commands they define will be available to the user as soon as Fusion starts.

- The user executes a script through the “Scripts and Add-Ins” command, and the execution stops immediately after the run function is complete. A script runs, and then it is done.
- An add-in is typically automatically loaded by Fusion when Fusion starts up. An add-in also usually creates one or more custom commands and adds them to the user interface during startup. The add-in continues to run throughout the Fusion session, so it can react whenever the user executes any of its commands. The add-in remains running until Fusion is shut down or the user explicitly stops it through the “Scripts and Add-Ins” dialog. When it stops, it cleans up whatever user interface customization it created in its stop function.

#### **4.2.2. Python vs. C++**

### **4.3. if necessary: changes to 3MF File Format**

### **4.4. slicer changes**

- how does it process 3mf per default?
- different possible approaches to solve the problem at hand and why did I do it the chosen way?

### **4.5. Implementation Design**

- software architecture (diagram?)
- input, output
- choices that had to be made

## Chapter 5.

### Results

- what does the optimised workflow look like?
- why is the solution good?
  - how are the results analysed / validated?
  - openly available → advantages of that
  - but: it is a proof of concept / prototype and thus will most likely not be the end of the story

## **Chapter 6.**

### **Conclusion**

#### **6.1. Outlook**

- communication with OrcaSlicer's owner softfever?
- option of code being pulled into other slicers
- what is left to do?

#### **6.2. Summary**

## Appendix A.

### Supplemental Information

```
1 <?xml version="1.0" encoding="utf-8"?>
2 <model xmlns="http://schemas.microsoft.com/3dmanufacturing/core
  /2015/02" unit="millimeter" xml:lang="en-US" xmlns:m="http:
  //schemas.microsoft.com/3dmanufacturing/material/2015/02"
  xmlns:p="http://schemas.microsoft.com/3dmanufacturing/
  production/2015/06" xmlns:b="http://schemas.microsoft.com/3
  dmanufacturing/beam lattice/2017/02" xmlns:s="http://schemas.
  microsoft.com/3dmanufacturing/slice/2015/07" xmlns:sc="http:
  //schemas.microsoft.com/3dmanufacturing/securecontent
  /2019/04">
3 <metadata name="Title" type="QName" preserve="1">Test v2</
  metadata>
4 <resources>
5   <m:colorgroup id="2">
6     <m:color color="#CC60FFFF" />
7     <m:color color="#A0A0A0FF" />
8   </m:colorgroup>
9   <object id="1" name="Body9" type="model" p:UUID="33f607be
    -287f-48ea-b893-8ee1626ed2b1" pid="2" pindex="0">
10     <mesh>
11       <vertices>
12         <vertex x="-39.484996" y="6.249999" z="30.000000" />
13         <vertex x="-37.568216" y="6.249999" z="30.000000" />
14         <vertex x="-37.568216" y="6.249999" z="33.000000" />
15         ...
16       </vertices>
17       <triangles>
18         <triangle v1="0" v2="1" v3="3" />
19         <triangle v1="3" v2="1" v3="2" />
20         <triangle v1="4" v2="0" v3="5" />
```

```
21         ...
22     </triangles>
23 </mesh>
24 </object>
25 </resources>
26 <build p:UUID="cd9553e5-fa90-4b4e-916e-bd1fed06979c">
27     <item objectid="1" p:UUID="91670927-ae59-46f3-cb97-91
28         a310462033" />
29 </build>
30 </model>
```

Listing A.1: Abbreviated Example of 3MF's 3dmodel.model File



## List of Figures

|                                                                                             |   |
|---------------------------------------------------------------------------------------------|---|
| 2.1. Iterative workflow in 3D printing highlighting the step to be optimized . . . .        | 3 |
| 3.1. Typical internal structure of 3MF file as exported from <i>Autodesk Fusion</i> . . . . | 6 |

## List of Tables

|                                             |   |
|---------------------------------------------|---|
| 3.1. Excerpt of 3MF document parts[3, p. 4] | 6 |
|---------------------------------------------|---|

## List of Listings

|                                                                |    |
|----------------------------------------------------------------|----|
| A.1. Abbreviated Example of 3MF's 3dmodel.model File . . . . . | 12 |
|----------------------------------------------------------------|----|

## Bibliography

- [1] N. Hudson, C. Alcock, and P. K. Chilana, “Understanding Newcomers to 3D Printing: Motivations, Workflows, and Barriers of Casual Makers,” in *Proceedings of the 2016 CHI Conference on Human Factors in Computing Systems*, ser. CHI '16. New York, NY, USA: Association for Computing Machinery, 2016, pp. 384–396. [Online]. Available: <https://dl.acm.org/doi/10.1145/2858036.2858266>
- [2] S. F. Autodesk Inc., CA, “Fusion Help | Creating a Script or Add-In | Autodesk,” 2025. [Online]. Available: <https://help.autodesk.com/view/fusion360/ENU/?guid=GUID-9701BBA7-EC0E-4016-A9C8-964AA4838954>
- [3] M. Consortium, “3MF Core Specification,” Feb. 2025. [Online]. Available: <https://3mf.io/spec/core-v1-3-0/>