

Product Service Notice

Doc: 076-8431-00

Rev: A

File: 98200-117-IX Date: 21 June 2016

Page 1 of 2

Equipment Line: Cardiology – Data Management

Subject: Sentinel Configuration for CardioExpress SL6A/12A/18A Orders

Affected: Sentinel (98200)

Applicability:

Mod Category: N/A Urgency: N/A Serial Number: N/A Time Required: N/A. In-Service: N/A

Dependency:

Applies only with "98410" series CardioExpress models SL6A, SL12A, SL18A.

Explanation:

These instructions describe an additional configuration for the Sentinel Cardiology Information Management System to send a worklist (orders) to "98410" series CardioExpress models SL6A, SL12A, and SL18A. This configuration is <u>in addition</u> to PSN 076-8169-00, CardioExpress Bi-Directional Configuration. It is compatible with the earlier 98400 series CardioExpress SL6/SL12, used in the same installation.

Implementation

Before making any changes, make a backup of the current file.

In a Sentinel Network environment, make the change on the Sentinel Server.

In a Sentinel Stand-alone configuration, make the change on the workstation.

Additional Configuration forSentinel 9 (all versions):

- management of the contract o	
Action	Expected result
Open testsToQueryResponse.xslt in a text editor in	Configuration file open
Administrator mode. Default location is "C:\Program Files	
(x86)\Del Mar Reynolds Medical\Sentinel Messaging	
Service\Steering Files\testsToQueryResponse.xslt"	
Search for the line containing " <record>"</record>	Line located
Insert the following text as a new line immediately after the	Line inserted. Note that this line
line located above:	should be present between
<serialno><xsl:value-of< td=""><td><record> and the line containing</record></td></xsl:value-of<></serialno>	<record> and the line containing</record>
select="OrderNumber"/>	<patientid></patientid>
Save the file, and then restart "Sentinel Messaging Service"	Service / computer restarts as
from services control panel or restart computer	necessary

COMPANY CONFIDENTIAL
FOR AUTHORIZED USE ONLY
© Spacelabs Healthcare 2016

Doc: 076-8431-00

Rev: A

File: 98200-117-IX Date: 21 June 2016

Page 2 of 2

Additional Configuration for Sentinel V10.0.0:

Action	Expected result
Open testsToQueryResponse.xslt in a text editor in Administrator mode. Default location is "C:\Program Files (x86)\Del Mar Reynolds Medical\Sentinel Messaging Service\Steering Files\testsToQueryResponse.xslt"	Configuration file open
Search for the line containing " <record>"</record>	Line located
Insert the following text as a new line immediately after the line located above: <serialno><xsl:value-of select="OrderID"></xsl:value-of></serialno>	Line inserted. Note that this line should be present between <record> and the line containing <patientid></patientid></record>
Save the file, and then restart "Sentinel Messaging Service" from services control panel or restart computer	Service / computer restarts as necessary

Known Issue

The CardioExpress cannot filter the order list, all orders will appear on every device.

Parts Required:

N/A

Tools and Equipment:

If necessary, an external disk drive with sufficient capacity to store the backup.

Parts Deposition:

N/A

Reporting:

N/A

Attachments:

N/A

COMPANY CONFIDENTIAL

FOR AUTHORIZED USE ONLY © Spacelabs Healthcare 2016