
$\Lambda = 0^\circ$
No loss
Exponential loss
VLM - undeformed
VLM - deformed
Root pitch angle [deg]
Airspeed [m/s]
0
1
2
3
4
5
6
7
0
20
40
60
80
100
120