

CITY OF OAKVIEW

Department of Building & Safety — Plan Review Division

July 14, 2026

RE: Plan Check No. BLD2026-0412

Project: Harbor Point Retail — Tenant Improvement

Address: 1400 Harbor Point Dr, Oakview, CA

Review Cycle: 1st Review

The plans and documents submitted for the above-referenced project have been reviewed for compliance with the 2022 California Building Code, as amended by the City of Oakview Municipal Code. The following comments must be addressed before a permit can be issued. Provide a written response to each comment and cloud all revisions on the resubmitted drawings.

BUILDING / ARCHITECTURAL

1. Sheet A-101: The occupant load calculation for the assembly area does not account for the fixed seating shown along the north wall. Recalculate the occupant load per CBC Table 1004.5 and revise the egress analysis accordingly.
2. Sheet A-201: The accessible route from the public right-of-way to the main entrance is not clearly identified. Provide a site plan detail demonstrating compliance with CBC 11B-402, including running slope and cross slope callouts.
3. The door schedule on Sheet A-601 lists Door 104 as a 32-inch clear width; however, this door serves an occupant load greater than 50 and is part of the required means of egress. Provide a minimum 36-inch door or justify per CBC 1010.1.1.

STRUCTURAL

4. Sheets S-201 and S-202: The new rooftop mechanical units exceed 400 lbs and no structural calculations were provided for the supporting members. Submit calculations stamped by the engineer of record demonstrating adequacy of the existing roof framing, or provide reinforcement details.
5. The lateral analysis references ASCE 7-16 while the cover sheet lists ASCE 7-22. Coordinate the referenced standards across the drawing set and calculations. This appears on multiple sheets and in the calculation package dated May 2, 2026.

FIRE / LIFE SAFETY

6. A fire sprinkler tenant improvement permit is required for the relocation of heads shown on Sheet FP-101. Submit a separate deferred submittal application through the Fire Prevention Bureau prior to rough inspection.
7. Sheet E-501: Exit signage is not shown at the corridor intersection adjacent to Room 118. Provide illuminated exit signage per CBC 1013.1 with battery backup.

ZONING / PLANNING

8. The proposed exterior signage shown on elevation Sheet A-301 is not part of this permit scope and requires a separate sign permit. Either remove the signage from the drawings or note it as "under separate permit." Contact the Planning Division at (555) 014-2200 with questions.

Please provide an itemized response letter addressing each comment above, along with two revised sets of plans. Incomplete resubmittals will be returned without review. If you have questions regarding building comments, contact the plan checker directly. Resubmittals may be made in person or through the ePlan portal.

Sincerely,

Diane Okafor, P.E.
Senior Plan Check Engineer
City of Oakview, Building & Safety
d.okafor@oakviewca.gov | (555) 014-2148